

Inspection Photos

API#081-07355

Operator: SWN

Insp#: 692402551

Insp Date: 9/23/20





Photo#1:
Establishment of Russian thistle across Location. _ Insert shows weed control efforts.

September 23, 2020



Photo#2:
Overview of Location to East, showing establishment of Scotch & Russian thistle.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

SWN PA Antietam API#081-07355