

Inspection Photos

API: 05-061-06576

Operator: ELLORA LLC

Inspection Date: 9/24/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06576 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing northeast toward the location. A two track road continues through the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06576 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing northeast at the east side of the location. Vegetation has uniformly established throughout the location and reflects the surrounding Blue grama grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06576 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing southwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06576 | Date: 9/24/2020

Inspection Photos



Photo 4. Facing south at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06576 | Date: 9/24/2020

Inspection Photos



Photo 5. Facing east at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06576 | Date: 9/24/2020

Inspection Photos




Photo 6. Facing northeast at the beginning of the vegetation transect performed at the location.



Photo 7. Facing southwest at the end of the vegetation transect performed at the location.



Inspection Photos




Photo 8. Facing south at the beginning of the vegetation transect performed at the reference area.



Photo 9. Facing north at the end of the vegetation transect performed at the reference area..



