



40.19983, -107.46435, 8086.4ft, 312°
09/28/2020 01:28:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Well location.

Texaco Sullivan NCT 1

API: 05-103-09258

Inspection: 700403637



40.20005, -107.46451, 8096.9ft, 323°
09/28/2020 01:28:01 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Texaco Sullivan NCT 1

API: 05-103-09258

Inspection: 700403637



40.19963, -107.4665, 8119.6ft, 34°
09/28/2020 01:33:53 PM



40.19952, -107.46658, 8133.7ft, 264°
09/28/2020 01:32:52 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator.

Texaco Sullivan NCT 1

API: 05-103-09258

Inspection: 700403637



40.19959, -107.46609, 8113.9ft, 19°
09/28/2020 01:31:32 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tanks.

Texaco Sullivan NCT 1

API: 05-103-09258

Inspection: 700403637



40.20016, -107.4645, 8070.1ft, 321°
09/28/2020 01:26:27 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Side of pump next to motor.

Texaco Sullivan NCT 1

API: 05-103-09258

Inspection: 700403637



40.20017, -107.46452, 8087.0ft, 128°
09/28/2020 01:27:24 PM



40.20016, -107.46449, 8090.6ft, 193°
09/28/2020 01:27:37 PM