

# Inspection Photos

API: 05-011-06148

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 9/24/2020



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-011-06148 | Date: 9/24/2020

## Inspection Photos



**Photo 1.** Facing south at the location. A crop has not been planted this season. It appears all equipment has been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-011-06148 | Date: 9/24/2020