





40.11089, -108.18703, 5939.6ft, 23°
09/28/2020 04:30:56 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403645





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Emission control devices & tanks.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403645





40.1113, -108.18688, 5929.8ft, 187°
09/28/2020 04:32:40 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tank off loading.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403645



40.11056, -108.1867, 5943.4ft, 29°
09/28/2020 04:29:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Weeds within tank secondary containment.

WRD Unit 29-33

API: 05-103-09920

Inspection: 700403645