



40.12414, -108.18766, 6067.6ft, 55°
09/28/2020 04:44:56 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

WRD Unit 20-33

API: 05-103-09925

Inspection: 700403649



40.12414, -108.18764, 6064.0ft, 65°
09/28/2020 04:45:14 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

WRD Unit 20-33

API: 05-103-09925

Inspection: 700403649



40.12414, -108.18764, 6064.0ft, 78°
09/28/2020 04:46:28 PM



40.12414, -108.18764, 6064.0ft, 95°
09/28/2020 04:46:54 PM



40.12414, -108.18764, 6064.0ft, 91°
09/28/2020 04:47:17 PM



40 12414, -108.18764, 6064.0ft, 159°
09/28/2020 04:48:30 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Storm water channel on west edge of location.

WRD Unit 20-33

API: 05-103-09925

Inspection: 700403649