

Inspection Photos  
Location Name: Steve J Pad  
Location ID: 333001



Photo 1: Tank Battery Sign



Photo 2: Load out bucket repaired





**Inspection Photos**  
**Location Name: Steve J Pad**  
**Location ID: 333001**



**Photo 3: Hole repaired**



**Photo 4: Unused riser**

