



Inspection Photos
081-05172
Remediation Project 10638
Location 312761
Inspection Date: 9/29/2020
All Photos taken by Kris Neidel

Photo #1 sign at wellhead.





Inspection Photos
081-05172
Remediation Project 10638
Location 312761
Inspection Date: 9/29/2020
All Photos taken by Kris Neidel

Photo #2 area of old land farm. The area was probed by HRL staff and COGCC staff for remaining signs of hydrocarbon (staining and odor), none was observed. Soil samples were collected for Lab analysis.



Inspection Photos
081-05172
Remediation Project 10638
Location 312761
Inspection Date: 9/29/2020
All Photos taken by Kris Neidel

Photo #3 area of old land farm. The area was probed by HRL staff and COGCC staff for remaining signs of hydrocarbon (staining and odor), none was observed. Soil samples were collected for Lab analysis.



Inspection Photos
081-05172
Remediation Project 10638
Location 312761
Inspection Date: 9/29/2020
All Photos taken by Kris Neidel

Photo #4 wellhead, well was SI at time of inspection.



Inspection Photos
081-05172
Remediation Project 10638
Location 312761
Inspection Date: 9/29/2020
All Photos taken by Kris Neidel

Photo #5 close-up of gauge seen in photo 4

