

Inspection Photos
Operator: Paradox
API: 113-06244
Date: 9/25/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the stormwater controls installed and maintained in the southern project area.



Photo 3. View of the wattles installed within the western project area.



Photo 4. View of the cable debris within the northwestern project area.



Photo 5. View of the reference area comprised of sagebrush shrubland with grasses such as blue grama.