

Inspection Photos
Location Name: Dechant X0-09
Location ID: 417941



Photo 1 WH sign




Photo 2 WH

Inspection Photos
Location Name: Dechant X0-09
Location ID: 417941



Photo 3 weeds overgrown around wellsite



Photo 4 TB sign

Inspection Photos
Location Name: Dechant X0-09
Location ID: 417941



Photo 5 TB




Photo 6 Horizontal Heated Separator

Inspection Photos Location Name: Dechant X0-09 Location ID: 417941



Colorado Oil & Gas Conservation Commission
 10521 Co Rd 41, Hudson, CO 80642, USA
 40.15318, -104.68168, 4836.9ft, T26
 09/30/2020 14:19:11



Colorado Oil & Gas Conservation Commission
 10521 Co Rd 41, Hudson, CO 80642, USA
 40.15319, -104.68177, 4845.6ft, 83°
 09/30/2020 14:19:56

Photo 7 Gas Meter Run

Photo 8 card in meter house indicates that calibration is not curren

Inspection Photos
Location Name: Dechant X0-09
Location ID: 417941



Photo 9 ECD