

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2020

Submitted Date:

10/01/2020

Document Number:

699102498**FIELD INSPECTION FORM**
 Loc ID 459550 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459545	WELL	XX	12/04/2018		123-48935	Guttersen C28-785	ND
459546	WELL	XX	12/04/2018		123-48936	Guttersen C28-770	ND
459547	WELL	XX	12/04/2018		123-48937	Guttersen C28-765	ND
459548	WELL	XX	12/04/2018		123-48938	Guttersen C28-775	ND
459549	WELL	XX	12/04/2018		123-48939	Guttersen C28-755	ND
459560	WELL	XX	12/05/2018		123-48948	Guttersen D09-765	ND
459561	WELL	XX	12/05/2018		123-48949	Guttersen D09-785	ND
459562	WELL	XX	12/05/2018		123-48950	Guttersen D09-775	ND
459563	WELL	XX	12/05/2018		123-48951	Guttersen D09-755	ND
459564	WELL	XX	12/05/2018		123-48952	Guttersen D09-770	ND

**General Comment:**[Not Drilled Location. No Oil & Gas activity.](#)

**Inspected Facilities**

Facility ID: 459545 Type: WELL API Number: 123-48935 Status: XX Insp. Status: ND

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459546 Type: WELL API Number: 123-48936 Status: XX Insp. Status: ND

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459547 Type: WELL API Number: 123-48937 Status: XX Insp. Status: ND

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459548 Type: WELL API Number: 123-48938 Status: XX Insp. Status: ND

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459549 Type: WELL API Number: 123-48939 Status: XX Insp. Status: ND

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459560 Type: WELL API Number: 123-48948 Status: XX Insp. Status: ND

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459561 Type: WELL API Number: 123-48949 Status: XX Insp. Status: ND

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 459562 Type: WELL API Number: 123-48950 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 459563 Type: WELL API Number: 123-48951 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 459564 Type: WELL API Number: 123-48952 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<b>COGCC Inspection Report Summary</b> On Thursday 10/1/20 at approximately 0956hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Guttarsen C 33-14 Pad of Noble Energy at Location ID: 459550 in Weld County, Colorado. While there, I observed a location that has not been drilled. No Oil & Gas activity. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.	burnsa	10/01/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102499	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5260629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5260629</a>