

# *Inspection Photos*

*API#107-06042*

*Operator: Booco's*

*Insp#: 692402571*

*Insp Date: 9/25/2020*



Photo#1:  
Over view of Location to Northwest.

September 25, 2020





Photo#2:  
Weed concerns at site.

September 25, 2020



Photo#3:  
Weed concerns at site.


Inspection Photos: Booco's PA Grassy Creek Coal API#107-06042





Photo#4:  
View along site to Southeast.

September 25, 2020



Photo#5:  
Area bare of vegetation.

Inspection Photos: Booco's PA Grassy Creek Coal API#107-06042