

Inspection Photos
Long Ridge J15
Spill/Release ID: 474500 Remediation: #15535
Inspection Date: September 24, 2020



J15 Pad sign.



Eastern area of the landfarm.

Inspection Photos
Long Ridge J15
Spill/Release ID: 474500 Remediation: #15535
Inspection Date: September 24, 2020



Eastern area of the landfarm.



Western area of the landfarm.

Inspection Photos
Long Ridge J15
Spill/Release ID: 474500 Remediation: #15535
Inspection Date: September 24, 2020



Spill/release area excavation.



Spill/release area excavation.



Inspection Photos
Long Ridge J15
Spill/Release ID: 474500 Remediation: #15535
Inspection Date: September 24, 2020



Monitoring well and cube container.



Fluid in the cube container with two distinct visible layer.



Inspection Photos
Long Ridge J15
Spill/Release ID: 474500 Remediation: #15535
Inspection Date: September 24, 2020



Fluid within the cube container.



Excavation, monitoring well and cube container as seen from the access road.

