

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402503262

Date Received:

10/05/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699102479

Inspection Date: 09/29/2020

FIR Submit Date: 09/29/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 438698

Location Name: Higgins Number: D19-720 County: \_\_\_\_\_  
Multi

Qtrqtr: NENE Sec: 19 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.216950 Longitude: -104.585870

FACILITY - API Number: 05-123- -00 Facility ID: 438698

Facility Name: Higgins Number: D19-720  
Multi

Qtrqtr: NENE Sec: 19 Twp: 3N Range: 64W Meridian: 6

Latitude: 40.216950 Longitude: -104.585870

CORRECTIVE ACTIONS:

1 ☒ CA# 142404

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."

Date: 10/02/2020

Response: CA COMPLETED

Date of Completion: 10/02/2020

Operator Comment: Noble has ensured all fittings have been fastened securely. See the attached file.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 142405

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/02/2020

Response: CA COMPLETED

Date of Completion: 10/02/2020

Operator  
Comment:

Noble energy has removed and properly disposed of the stained soil. See the attached file

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 10/5/2020 11:24:42 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402503262	FIR RESOLUTION SUBMITTED
402503271	Higgins_D19-720_Photos

Total Attach: 2 Files