

Inspection Photos
Location Name: CECIL USX /AB35-11D
Location #: 422514



Photo #1

Cecil USX AB35-12D (05-123-33291) Wellsite
Temporarily Abandoned | TA



Photo #2

Cecil USX AB35-11D (05-123-33294) Wellsite
Temporarily Abandoned | TA

Inspection Photos

Location Name: CECIL USX /AB35-11D

Location #: 422514



Photo #3

Cecil USX AB35-12D, 11D, 14 Battery site

Abandoned: ALL Equipment Removed

Formerly served Dyer - USX AB 35-13

(Plugged & Abandoned | PA)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources