

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2020

Submitted Date:

10/07/2020

Document Number:

696103791

FIELD INSPECTION FORM

Loc ID 422514 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422510	WELL	TA	05/04/2020	OW	123-33291	CECIL USX AB35-12D	TA
422516	WELL	TA	05/04/2020	OW	123-33294	CECIL USX AB35-11D	TA

General Comment:

This is a WELL / ABANDONED BATTERY inspection.
Well(s): 2: Temporarily Abandoned | TA.
Battery: Abandoned. ALL equipment has been removed.
Abandoned Battery SE corner GPS coordinates: 40.526480, -104.523320

Abandoned Centralized Battery formerly served 3 Location IDs (422514, 302231, 306371).
(Well(s): 3: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	2: Wellsites.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	2: Wellsites. Iron panel.		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	2: Wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 422510 Type: WELL API Number: 123-33291 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Battery Abandoned: All Equipment Removed.
 COGCC records indicate last production: 02/2017.
 SI/TA well per variance doc. #401474555. (NOBLE).
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

 Form 4 Sundry doc. #402373044 indicates Temporarily Abandoned | TA status date:
 12/18/2018.

Corrective Action: _____ Date: _____

Facility ID: 422516 Type: WELL API Number: 123-33294 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
 Battery Abandoned: All Equipment Removed.
 COGCC records indicate last production: 02/2017.
 SI/TA well per variance doc. #401474555. (NOBLE).
 Yellow LTSI & Orange Facility Decommissioned tags for SI/TA status present at wellsite.
 Locked-Out, Tagged-Out | LOTO.

 Form 4 Sundry doc. #402372867 indicates Temporarily Abandoned | TA status date:
 12/18/2018.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 10/06/2020 at approximately 12:04 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: CECIL USX /AB35-11D Location ID: 422514 Well Names: Cecil USX AB35-12D, Cecil USX AB35-11D API: 05-123-33291, 05-123-33294 Location County: Weld County, Colorado Weather: Mostly clear w/ haze, dry.</p> <p>While there, I observed: Well(s): 2: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.526480, -104.523320</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (422514, 302231, 306371). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/07/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103792	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264125