

Inspection Photos

Location Name: HOWARD-66N64W /34NWNW

Location #: 408610




Photo #1

Howard A34-4 (05-123-14818)

Abandoned Location | AL

~ 220 yds.

No disturbance or evidence of oil & gas activity.

prior insp.