

Inspection Photos

Location Name:

Gittlein D04-24, Marie D 4-72 Tank Battery

Facility ID: 447618




Photo #1 Tank Battery



Photo #2 Production Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name:

Gittlein D04-24, Marie D 4-72 Tank Battery

Facility ID: 447618



Photo #3 Stained Soil



Photo #4 Stained Soil

Inspection Photos

Location Name:

Gittlein D04-24, Marie D 4-72 Tank Battery

Facility ID: 447618



Oct 7, 2020 at 8:04:12 AM
+40.2480, -104.5549

Weid

Colorado Oil & Gas Conservation Commission

Photo #5 Pit needs secondary containment/ berms



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources