

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2020

Submitted Date:

10/07/2020

Document Number:

699102548**FIELD INSPECTION FORM**Loc ID 332791 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                  | Comment                         |
|--------------|-------|--|---------------------------------|
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 298854      | WELL | PR     | 07/20/2020  | OG         | 123-29172 | HANSCOME C 28-28D | PR          |
| 298940      | WELL | SI     | 05/01/2019  | OW         | 123-29209 | HANSCOME C 28-29D | SI          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |          |             |
|--------------------|----------|-------------|
| Comment:           | Adequate |             |
| Corrective Action: |          | Date: _____ |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Panel    |       |  |
| Corrective Action: |          | Date: |  |

**Equipment:**

|                    |                                  |       |                 |
|--------------------|----------------------------------|-------|-----------------|
|                    |                                  |       | corrective date |
| Type: Plunger Lift | # 2                              |       |                 |
| Comment:           |                                  |       |                 |
| Corrective Action: |                                  | Date: |                 |
| Type: Bradenhead   | # 2                              |       |                 |
| Comment:           | Appear to be plumbed to surface. |       |                 |
| Corrective Action: |                                  | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 298854 Type: WELL API Number: 123-29172 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Facility ID: 298940 Type: WELL API Number: 123-29209 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: SI.

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <b>COGCC Inspection Report Summary</b><br>On Wednesday 10/7/20 at approximately 1011hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Hanscome C 64N64W28NENW of Noble Energy at Location ID: 332791 in Weld County, Colorado.<br>While there, I observed 1 well that is producing and 1 well that is shut in.<br>No violation of the COGCC rules were observed at the time of inspection.<br>This is a summary of inspection report. | burnsa | 10/07/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 699102549    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264284">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5264284</a> |