

Inspection Photos
Location Name: HSR Cowan 5-35
API # 123-16214




Wellhead

Inspection Photos
Location Name: HSR Cowan 5-35
API # 123-16214



Unused equipment on 7/8/2020



Unused equipment on 10/7/2020