

Inspection Photos
Operator: BP America
API: 067-07544
Date: 10/1/2020



Photo 1. View of the project area from the southeastern corner facing center.




Photo 2. View of the northern project area from the northeastern corner facing westward. Vegetation appears to be progressing here largely with rubber rabbitbrush. Russian thistle debris observed throughout project area.



Photo 3. View of dense Russian thistles growing on the well pad, need to be removed and properly disposed of.



Photo 4. View of reference area vegetation comprised of dense rubber rabbitbrush with understory of grasses such as sand dropseed and western wheatgrass.