

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 3 – Berms repaired and Barbed Wire Fence installed around Tank Battery

Photo 4 – Tank

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 5 – Pumping Unit, weeds removed

Photo 6 – Weeds removed from Wellhead

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 7 – Stained Soil removed from Exhaust

Photo 8 – Proper Labeling installed on Skim Tank

Inspection Photos
Location Name: Weld County Kindt 1
Location ID: 327811



Photo 9 – Pit