

Inspection Photos

Operator: Southland Royalty
API: 067-08899
Date: 10/1/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation appears to be progressing here largely with cattails, *Phalaris* sp., and western wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing northward.



Photo 4. View of dense Canada thistles (approx. 1000 indiv.) within the western project area.