





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Excavation.

Fork Unit 3-15-1-2

API: 05-103-08924

Inspection: 700403791



39.96399, -108.8302, 6034.9ft, 38°
10/07/2020 03:11:32 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Excavation..

Fork Unit 3-15-1-2

API: 05-103-08924

Inspection: 700403791