

Inspection Photos
Location Name: GARCIA USX AB /35-23
Location #: 422237



Photo #1

Garcia USX AB 35-23 (05-123-33195) Wellsite

Shut-In | SI



Photo #2

Garcia USX AB 35-10D (05-123-33201) Wellsite

Shut-In | SI

Inspection Photos

Location Name: GARCIA USX AB /35-23

Location #: 422237



Photo #3

Torres-USX AB 35-9, Garcia USX AB 35-23, 10D

Battery site

Inactive | Shut-down