

Inspection Photos

Location Name: Lang USX AB /35-03 (Multi)

Location #: 422547




Colorado Oil & Gas Conservation Commission
40.53525, -104.51996, 4758.0ft, 222°
10/08/2020 16:38:07

Photo #1

Lang USX AB 35-03 (05-123-33303) Wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.53513, -104.51991, 4773.0ft, 315°
10/08/2020 16:38:31

Photo #2

Lang USX AB 35-19D (05-123-33308) Wellsite

Shut-In | SI

Inspection Photos

Location Name: Lang USX AB /35-03 (Multi)

Location #: 422547



Colorado Oil & Gas Conservation Commission
40.53511, -104.51983, 4777.1ft, 314°
10/08/2020 16:38:49

Photo #3

Lang USX AB 35-05D (05-123-33309) Wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.53683, -104.51995, 4788.2ft, 104°
10/08/2020 17:15:48

Photo #4

Lang USX AB 35-03, 19D, 05D,

Lang-USX AB 35-6

Battery site

Inactive | Shut-down