

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 1 – South Wellheads, Weeds need removed and controlled

Photo 2 – North Wellheads

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 3 – 8-60-17-20-2 Wellhead, Weeds

Photo 4 – 8-60-17-8-5 Wellhead, Weeds

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 5 – Secondary Containment needs Wildlife Netting

Photo 6 – Unmarked Riser

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131




Photo 7 – Stained Soil at West Separator

Photo 8 – Stained Soil at Middle Separator

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 9 – Compressor and VRUs



Photos 10 – Unused Parts

Inspection Photos
 Location Name: Hunt 8-60-17A PAD
 Location ID: 457131



Photo 11 Gas Meters, Weeds

Photos 12 – Gas Meter Calibration Cards from East Shed

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 13 – Gas Meter Calibration Cards from West Shed

Photos 14 – Separators, Weeds in the NW Corner

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 15 – Tank Battery and VRTs




Photos 16 – Tank Battery Sign

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 17 – Stained Soil at the Recycle Pump



Photos 18 – Stained Soil at North VRT

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 18 – Stained Soil at North VRT



Photos 19 – Stained Soil at Tanks

Inspection Photos
Location Name: Hunt 8-60-17A PAD
Location ID: 457131



Photo 20 – Stained Soil at Tanks