

Inspection Photos  
Location Name: Wagner 2-1  
Location ID: 323293



Tank battery



Wellhead

**Inspection Photos**  
**Location Name: Wagner 2-1**  
**Location ID: 323293**



**Debris on 7/15/2020**



**Debris on 10/9/2020**

**Inspection Photos**  
**Location Name: Wagner 2-1**  
**Location ID: 323293**




**Master valve leak and stained soil on 7/15/2020**



**Master valve leak and stained soil on 10/9/2020**

**Inspection Photos**  
**Location Name: Wagner 2-1**  
**Location ID: 323293**



**Calibration card on 10/9/2020**