

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2020

Submitted Date:

10/09/2020

Document Number:

696103819**FIELD INSPECTION FORM**Loc ID 422237 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422223	WELL	SI	09/01/2016	OW	123-33195	GARCIA USX AB 35-23	SI
422230	WELL	SI	05/01/2017	OW	123-33201	GARCIA USX AB 35-10D	SI

General Comment:

This is a WELL inspection.
Well(s): 2: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (306365, 422237).
(Well(s): 3: Shut-In | SI).

Refer to Field Inspection Report doc. #696103817 and/or Location ID #306365
for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	2: Wellsites.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696103817 and/or Location ID #306365 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	2: Wellsites. Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696103817 and/or Location ID #306365 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 2			corrective date
Comment:	2: Wellsites. Appears plumbed to surface.			
Corrective Action:				Date:
Type: Plunger Lift	# 2			
Comment:	2: Wellsites.			
Corrective Action:				Date:
Type:	#			
Comment:	Refer to Field Inspection Report doc. #696103817 and/or Location ID #306365 for Battery / Facility, Equipment info.			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS		
			CENTRALIZED BATTERY		40.529251,-104.507955		
Comment:		Centralized Battery serves 2 Location IDs (306365, 422237). Refer to Field Inspection Report doc. #696103817 and/or Location ID #306365 for Battery / Facility, Equipment info.					
Corrective Action:						Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 422223 Type: WELL API Number: 123-33195 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
COGCC records indicate last production: 08/2016.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action: Date: Facility ID: 422230 Type: WELL API Number: 123-33201 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
COGCC records indicate last production: 04/2017.
SI/TA well per variance doc. #401474555. (NOBLE).
Yellow LTSI tag for SI/TA status present at wellsite.
Locked-Out, Tagged-Out | LOTO.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 10/08/2020 at approximately 14:33 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: GARCIA USX AB /35-23 Location ID: 422237 Well Names: Garcia USX AB 35-23, Garcia USX AB 35-10D API: 05-123-33195, 05-123-33201 Location County: Weld County, Colorado Weather: Mostly clear w/ haze, dry.</p> <p>While there, I observed: Well(s): 2: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (306365, 422237). (Well(s): 3: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696103817 and/or Location ID #306365 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/09/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103820	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5266183