

**Inspection Photos**  
**Location Name: Suckla Brown Unit 17**  
**Location ID: 318596**



**Pic 1 stained soil on manifold**



**Pic 2 stained soil where flow lines come into manifold**

# Inspection Photos

**Location Name: Suckla Brown Unit 17**  
**Location ID: 318596**



**Pic 3**

**Pic 4**

Inspection Photos  
Location Name: Suckla Brown Unit 17  
Location ID: 318596



Pic 5



Pic 6