


Inspection Photos
Location Name: Moran 1
Location ID: 319771



Pic 1 mechanical issue on valve on casing line venting gas



Pic 2 mechanical issue on valve on casing line venting gas

Inspection Photos
Location Name: Moran 1
Location ID: 319771



Pic 3



Pic 4