

Final Reclamation Inspection

October 7, 2020

Operator: MERIT ENERGY COMPANY - #56565

Location ID: 319665

Inspection Document #: 697502053

Adams County, CO

NENE Section 3 T1S R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 1. Photo taken from the location. Photo illustrates Operator has failed to remove all equipment.

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 2. Photo taken from the location. Photo illustrates an unmanaged List B Colorado noxious weed, Musk thistle. Musk thistle was observed throughout the location.

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 3. Photo taken from the location. Photo illustrates a rosette of a List B Colorado noxious weed, Musk thistle, and cheatgrass (dead grass vegetation), a List C Colorado noxious weed.

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 4. Photo taken from the location, facing West. Photo illustrates unmanaged List C Colorado noxious weeds, Common mullein. Common mullein was observed throughout the location.

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 5. Photo taken from the location, facing South. Photo illustrates unmanaged List B Colorado noxious weeds, Scotch thistle. Scotch thistle was primarily observed along the western portion of the location.

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 6. Photo taken from the location. Photo illustrates Operator has failed to remove the guy line anchor and t-post. All four guy line anchors remain at location.

Inspection Photos
Location Name: BERGMAN #1
Location ID: 319665



Photo 7. Reference photo taken east of the location, facing East. Photo illustrates the vegetative difference of the nearby reference area compared to the location.