

Final Reclamation Inspection

October 7, 2020

Operator: MERIT ENERGY COMPANY - #56565

API: 05-001-09556

Inspection Document #: 697502061

Adams County, CO

NWSW Section 4 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ZARLENGO #13-4
Location ID: 332818



Photo 1. Photo taken east of the location, facing West. Photo illustrates the well was not drilled at the proposed well location based off field observations. This inspection confirms only one well has been drilled at location by another operator.