

BP L48 San Juan



V2 Compliance Follow Up Form

18157537882

Reference Number:

20201005-18157537882

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Submission Date:

Oct 5, 2020 3:42:30 PM MDT

Location:

232 Co Rd 335, Ignacio, CO 81137, USA

Oct 5, 2020 3:41:21 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Sep 30, 2020
Well Name	PINE RIVER 03-31 1
API Number	50670648100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Land Owner Debris Repaired Berm


Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up trash

Photo of third corrective action completed



Completed work description of corrective action 3

Fixed berm

Photo of fourth corrective action completed



Completed work description

Installed rock run down

Completed work description of corrective action 4

Fixed erosion

Additional photos



Summary of all work completed

Compliance, installed rock run downs, fixed erosion picked up trash and fixed berm