

BP L48 San Juan



V2 Compliance Follow Up Form

18158265496

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20201012-18158265496

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Oct 12, 2020 3:36:00 PM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Oct 12, 2020 3:38:57 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Oct 6, 2020

Well Name

SMITH GAS UNIT A 1

API Number

50670743100

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

location photo

Photo of third corrective action completed



**Completed work description of corrective
action 3**

location photo

Photo of fourth corrective action completed

**Completed work description**

removed and bagged seedheads from
reclamation area

**Completed work description of corrective
action 4**

removed and bagged seedheads from location

Additional photos



Completed work description

Summary of all work completed

removed weeds from location

previous treatment dates 6/16/16, 7/13/17,
7/16/18, 9/16/19, 6/25/20