



Mr. David Tewkesbury  
Crestone Peak Resources Operating LLC  
10188 E. Interstate 25 Frontage Road  
Firestone, CO 80504

October 12, 2020

**RE: Colorado Oil & Gas Conservation Commission (COGCC)  
Vegetation Assessment Report (Final Reclamation Completion Notice)  
HALEY-GUMESON-62N67W /32CSE (Location ID: 319019)  
Crestone Peak Resources Operating LLC (Operator: 10633)**

Dear Mr. Tewkesbury:

Apex Companies, LLC (Apex) is presenting this letter to Crestone Peak Resources Operating LLC (Crestone) documenting the results of a vegetation assessment that demonstrates successful completion of final reclamation efforts, per COGCC Rule 1004, on the above-referenced location in Colorado. Attached is a topographic location map and a site map with additional location information.

Site visits, project correspondence and documentation, and the completed vegetation assessment confirmed that the location has been final reclaimed and returned by the landowner to cropland and agricultural use, with no evidence of unrestored subsidence over two growing seasons. Based on the results of the survey, final reclamation, as defined by COGCC Rule 1004.a and 1003.e (1), has been achieved. Photographs required by COGCC Rule 1003.e (3) are attached, along with the site diagram that illustrates the photo points.

On May 28, 2020, the site was visited and four photographs documenting crop establishment and site conditions were taken, along with one photograph illustrating reference area crops.

Apex appreciates the opportunity to provide environmental consulting services on this project. Should you have any questions or require additional information, please do not hesitate to contact me.

Sincerely,  
**Apex Companies, LLC**

A handwritten signature in black ink that reads 'Adam Roll'.

Adam Roll  
Environmental Scientist  
970-589-6111  
adam.roll@apexcos.com

**Attachments:**


1. Topographic Location Map
2. Vegetation Survey Site Map
3. Vegetation Survey Photos



Topographic Location Map

CRESTONE PEAK  
RESOURCES OPERATING  
LLC

HALEY-GUMESON-62N67W /32CSE  
(319019)





## Vegetation Survey Site Map

**CRESTONE PEAK  
RESOURCES OPERATING  
LLC**

**HALEY-GUMESON-62N67W /32CSE  
(319019)**

	Vegetation Photo Point
	Directional Photos

Legal Description: C SE, Sec. 32, T2N-R67W

Lat/Long: 40.091148/-104.909803

County: Weld

Land Use: Crop Land

Inspector: A. Roll

Assessment Date: 5/28/2020

Aerial Imagery Date: 10/6/2014

*\*Please reference coordinate disclaimer on the photo log pages.*



# Vegetation Assessment Photo Log

Date Completed - 05/28/2020

Client - Crestone Peak Resources Operating LLC

Location Name (ID) - HALEY-GUMESON-62N67W /32 CSE (319019)



Photo Point A: North of Disturbance - Facing South



Photo Point B: South of Disturbance - Facing North



Photo Point C: West of Disturbance - Facing East



Photo Point D: East of Disturbance - Facing West

\*Geographic coordinates provided in the borders of all attached photos are based on points identified by the mobile phone or tablet which collected the photo. Coordinate accuracy in this format is typically no greater than 5 meters, while the points illustrated in the site diagram associated with this submittal were collected with a high accuracy GPS unit with sub-meter accuracy. Discrepancies between the site diagram and photo coordinates will exist.

# Vegetation Assessment Photo Log

Client - Crestone Peak Resources Operating LLC

Date Completed - 05/28/2020

Location Name (ID) - HALEY-GUMESON-62N67W /32 CSE (319019)




Photo Point E: Reference Crop Vegetation - Facing South