

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | | corrective date |
|-----------------------------|-----|-------|-----------------|
| Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-----------------------------------------------------------------------|----------|-------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | , |
| Comment: | <input type="text" value="Shares containment with crude oil tanks."/> | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|-----------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |

| | |
|--------------------------|--|
| Other (Capacity) 48 BBLS | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | 40.283800,-104.527200 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Metal | Adequate | Walls Sufficent | Base Sufficent | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 447439 Type: TANK API Number: - Status: AC Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 10/13/20 at approximately 1317hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Dinnel 01,03,C26-20 Tank Battery of Noble Energy Facility ID: 447439 in Weld County, Colorado. While there, I observed a Tank Battery that is shut in. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p> | burnsa | 10/13/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 699102613 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5268888 |