

Facility ID: 444630



Colorado Oil and Gas Conservation Commission
40.00788, -104.89172, 5027.1ft, 101°
09/23/2020 01:42:56 PM

Photo 2 – Stormwater runoff north of former battery/remediation excavation. Sparse/ dead vegetation in area of runoff

Inspection Photos
Location Name: Charter Schneider Tank Battery
Facility ID: 444630



Photo 3 – Stormwater runoff north of former battery/remediation excavation.



Photo 4 – Stormwater runoff north of former battery/remediation excavation.

Inspection Photos
Location Name: Charter Schneider Tank Battery
Facility ID: 444630



Photo 5 – Stormwater runoff north of former battery/remediation excavation.



Photo 6 – Stormwater runoff north of former battery/remediation excavation.

Inspection Photos
Location Name: Charter Schneider Tank Battery
Facility ID: 444630



Photo 7 – Soil sample 1; taken from soil runoff area with no vegetation. Soils are very well compacted.



Photo 8 – Soil sample 2; taken from soil runoff area with no vegetation. Soils are very well compacted.