

## Inspection Photos

Location Name: Kelley Young Jensen B-1

Location ID: 322292 & Spill/Release ID: 476600

Inspection Date: September 29, 2020



**Location from the access road.**



**Approximate area of where the well head was located.**



## Inspection Photos

Location Name: Kelley Young Jensen B-1

Location ID: 322292 & Spill/Release ID: 476600

Inspection Date: September 29, 2020



**Approximate area of where the tank battery was. Note, Utah Gas collected soil samples from beneath the tank battery.**

