

Inspection Photos

API#081-06869

Operator: HRM Resources

Inspection Number: 692402558

Inspection Date: 11/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to South. Road loop still visible; gravel not removed

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06869



Photo#2:
View North up access road exiting Location.



Photo#3:
Overview of Location to North; note bare ground areas

September 24, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Sand Hills Fed API#081-06869



Photo#4:
Graveled areas

September 24, 2020



Photo#5:
Views of Reference Area.

September 24, 2020