

Inspection Photos

API#081-06630

Operator: HRM Resources

Inspection Number: 692402562

Inspection Date: 9/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View into Location to Northeast; note tracking into Location.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources


Inspection Photos: HRM Res PA Hedges API#081-06630



Photo#2:

View back to entry to Southwest; note tracking into Location. Insert close up of vegetation and ground conditions.

September 24, 2020



Photo#3:
Access road has not been reclaimed.



Photo#4:
Weedy area of Location.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Hedges API#081-06630



Photo#5:
Reference area.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Hedges API#081-06630