

Inspection Photos

API#081-06632

Operator: HRM Resources

Inspection Number: 692402557

Inspection Date: 11/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location at point where access road entered location. Note vehicle impact.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Battle Mtn API#081-06632



Photo#2:
View South of reclaimed road accessing Location.
Note signs of vehicle trafficking.

September 24, 2020



Photo#3:
Vegetation establishment on former road.



Photo#4:
Overview of Location to North.

September 24, 2020



Inspection Photos: HRM Res PA Battle Mtn API#081-06632



Photo#5:
Overview of Location to East.

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Battle Mtn API#081-06632



Photo#6:
Overview of Location to West. Insert; vegetation in depression area

September 24, 2020



Photo#7:

Views of Reference Area. South end of site abuts to Pasture planted to Crested Wheat

September 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA Battle Mtn API#081-06632