

Inspection Photos

API: 071-07742

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/8/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07742 | Date: 10/8/2020

Inspection Photos



Photo 1. Facing south toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/8/2020

Inspection Photos



Photo 2. Facing south toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/8/2020

Inspection Photos



Photo 3. Facing northeast along the fill slope. The powerline utility remains to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/8/2020

Inspection Photos



Photo 4. The powerline cable has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/8/2020

Inspection Photos



Photo 5. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07742 | Date: 10/8/2020