

## Inspection Photos

Location Name: Champlin 248 Amoco C 2

Location ID: 320066

Oct 15, 2020 at 11:46:37 AM  
39.831370,-104.552841  
Watkins CO 80137  
United States  
COGCC



Pic 1

Oct 15, 2020 at 11:47:11 AM  
39.831765,-104.552434  
Watkins CO 80137  
United States  
COGCC



Pic 2



## Inspection Photos

Location Name: Champlin 248 Amoco C 2

Location ID: 320066

Oct 15, 2020 at 11:48:12 AM  
39.831881,-104.552724  
Watkins CO 80137  
United States  
COGCC



**Pic 3 weeds in manifold area.**

Oct 15, 2020 at 11:48:29 AM  
39.831884,-104.552583  
Watkins CO 80137  
United States  
COGCC



**Pic 4 weeds in tank berm.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources