

**Inspection Photos**  
**Operator: BP America**  
**API: 067-09481**  
**Date: 10/13/2020**



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Revegetation is progressing with crested wheatgrass, sand dropseed, and rubber rabbitbrush.



Photo 3. View of reference area vegetation comprised of pinyon and juniper woodland with and understory of sagebrush, squirreltail, Indian ricegrass, and mixed forbs.