

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2020

Submitted Date:

10/16/2020

Document Number:

693503613**FIELD INSPECTION FORM**

Loc ID 440718	Inspector Name: Silver, Randy	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 12 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10110</u> Name of Operator: <u>GREAT WESTERN OPERATING COMPANY LLC</u> Address: <u>1001 17TH STREET #2000</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440717	WELL	XX	01/28/2015	LO	001-09842	Schaefer 25-1-4HC	XX
442462	WELL	SI	03/08/2019	LO	001-09849	Schaefer LD 13-029HC	DG
443366	WELL	PR	11/01/2017	OW	001-09858	Schaefer 2536-1-4HC	PR
443367	WELL	XX	09/29/2015	LO	001-09859	Schaefer 24-3-3HC	XX
443368	WELL	PR	01/01/2019	OW	001-09860	Schaefer 2413-3-15HN	PR
443369	WELL	XX	09/29/2015	LO	001-09861	Schaefer 25-1-6HC	XX
443370	WELL	XX	09/29/2015	LO	001-09862	Schaefer 24-3-4HN	XX
443371	WELL	DG	03/07/2019	LO	001-09863	Schaefer LD 13-029HN	DG
443372	WELL	DG	12/01/2018	LO	001-09864	Schaefer LD 13-030HXX	DG
443374	WELL	PR	04/01/2019	OW	001-09866	Schaefer LD 13-031HN	PR
443375	WELL	XX	09/29/2015	LO	001-09867	Schaefer 24-3-6HN	XX
443376	WELL	XX	09/29/2015	LO	001-09868	Schaefer 24-3-5HC	XX
443377	WELL	XX	09/29/2015	LO	001-09869	Schaefer 25-1-7HN	XX
458703	WELL	PR	04/27/2019	OW	001-10253	Schaefer LD 13-033HN	PR
458704	WELL	PR	04/21/2019	OW	001-10254	Schaefer LD 13-032HC	PR
458705	WELL	PR	04/27/2019	OW	001-10255	Schaefer LD 13-032HN	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	440717	Type:	WELL	API Number: 001-09842 Status: XX Insp. Status: XX
Facility ID:	442462	Type:	WELL	API Number: 001-09849 Status: SI Insp. Status: DG
Facility ID:	443366	Type:	WELL	API Number: 001-09858 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:				Date:
Facility ID:	443367	Type:	WELL	API Number: 001-09859 Status: XX Insp. Status: XX
Facility ID:	443368	Type:	WELL	API Number: 001-09860 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:				Date:
Facility ID:	443369	Type:	WELL	API Number: 001-09861 Status: XX Insp. Status: XX
Facility ID:	443370	Type:	WELL	API Number: 001-09862 Status: XX Insp. Status: XX
Facility ID:	443371	Type:	WELL	API Number: 001-09863 Status: DG Insp. Status: DG
Facility ID:	443372	Type:	WELL	API Number: 001-09864 Status: DG Insp. Status: DG
Facility ID:	443374	Type:	WELL	API Number: 001-09866 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			
Corrective Action:				Date:
Facility ID:	443375	Type:	WELL	API Number: 001-09867 Status: XX Insp. Status: XX
Facility ID:	443376	Type:	WELL	API Number: 001-09868 Status: XX Insp. Status: XX
Facility ID:	443377	Type:	WELL	API Number: 001-09869 Status: XX Insp. Status: XX
Facility ID:	458703	Type:	WELL	API Number: 001-10253 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	PR			

Corrective Action:		Date:	
Facility ID: <u>458704</u> Type: <u>WELL</u> API Number: <u>001-10254</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<u>PR</u>		
Corrective Action:		Date:	
Facility ID: <u>458705</u> Type: <u>WELL</u> API Number: <u>001-10255</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<u>PR</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Tracking Pad	Pass			

Comment:

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Inspection due to XX wells. XX wells appear to have not been drilled yes and 3 wells in drilling status appear to have cellar installed and surface casing installed.	silverr	10/16/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503614	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272109">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5272109</a>