

Inspection Photos
Facility Name: KPK Facility 4 North
Facility ID: Spill/Release Point 477605



Liquid hydrocarbons emerging through cracked pavement on Tipple Parkway



Looking west along Tipple Parkway