

Inspection Photos

Location Name: Nauroth 68S96W 2NESE pad & SGV 2I Spill/Release

Location ID: #334413 & Spill/Release ID: 478244

Inspection Date: October 16, 2020



Photo #1 – Sign at entrance to pad.



Photo #2 – View of wellheads from southwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Nauroth 68S96W 2NESE pad & SGV 2I Spill/Release

Location ID: #334413 & Spill/Release ID: 478244

Inspection Date: October 16, 2020



Photo #3 – Heated horizontal separators on south end of pad.



Photo #4 – View of tank battery from west.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Nauroth 68S96W 2NESE pad & SGV 2I Spill/Release

Location ID: #334413 & Spill/Release ID: 478244

Inspection Date: October 16, 2020



Photo #5 – Vegetation growth inside of secondary containment area.



Photo #6 – View of excavation on south end of pad, looking south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Nauroth 68S96W 2NESE pad & SGV 2I Spill/Release

Location ID: #334413 & Spill/Release ID: 478244

Inspection Date: October 16, 2020



Photo #7 – View of north side of excavation, looking west.



Photo #8 – View into excavation, from south.

