

Inspection Photos
Location Name: O'Hara 2-9
Location ID: 318513



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: O'Hara 2-9
Location ID: 318513



Photo 3 Pump Jack



Photo 4 Vertical Separator

Inspection Photos
Location Name: O'Hara 2-9
Location ID: 318513



Photo 5 Crude oil tank



Photo 6 Tank berm flattened out

Inspection Photos
Location Name: O'Hara 2-9
Location ID: 318513




Photo 7 Tank berm flattened out




Photo 8 Tank berm flattened out