

Inspection Photos
Location Name: Klien #1
Location ID: 318289



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Klien #1
Location ID: 318289



Photo 3 Horizontal Heated Separator



Photo 4 TB

Inspection Photos
Location Name: Klien #1
Location ID: 318289



Photo 5 TB sign



Photo 6 Gas Meter Run card indicates current calibration

Inspection Photos
Location Name: Klien #1
Location ID: 318289



Photo 7 Gas Meter Run




Photo 8 Gas Meter Run card indicates current calibration